

CARE INSTRUCTIONS

PAINT SURFACE COATINGS

Do not wash the vehicle with any car wash/shampoo for the first 3 days. HYDRO G9+ has a unique curing process that takes around 3 days and during this time use only clear water to remove contaminants from the surface.

Once the curing time has elapsed, follow the instructions as below:

- Hand wash your vehicle as required using a pH neutral car wash/shampoo.
- We recommend using HYDRO G9+ Shampoo which has been formulated to be completely compatible with your paint surface coating. HYDRO G9+ Shampoo can be purchased from your selling dealership or by contacting MotorOne in your state.
- Avoid using car washes/shampoos that contain degreasers or solvents and do not polish the vehicle. These products may affect the life of the coating.
- Do not take the vehicle through automated car washes that use abrasive washing actions or harsh chemicals - this also has the potential to damage the coating.

Step 1: Prior to washing, thoroughly hose your vehicle to dislodge loose dirt/contaminates. Washing your car in the shade when the metal is cool will prevent premature evaporation of the HYDRO G9+ shampoo and produce the best results.

Step 2: Mix 2 caps of HYDRO G9+ shampoo in a 10 litre bucket of water (warm water if possible).

Step 3: Use a clean sponge and dip into the bucket, washing the vehicle from top panels down. Rinse the sponge after washing each panel to dislodge any contaminants that may have accumulated in the sponge during the washing process.

Step 4: Thoroughly rinse the shampoo residue from your vehicle.

Step 5: For best results, chamois the vehicle dry using a good quality chamois or soft cloth.

TO REMOVE BIRD, BAT & BUG STAINS:

- Contaminates such as bird & bat droppings, tree sap and bug splatter are highly corrosive and should be removed from the painted surface of your vehicle as soon as possible.
- Do not scrub, pick-off the stain or use any abrasive cleaners. This may damage the painted surface.
- Use neat (undiluted) HYDRO G9+ shampoo on the affected area allowing the shampoo to soak and moisten the area before removing, then wash as per above instructions.
- In the event you are unsuccessful in removing the contaminate, contact MotorOne in your state.

MOTORONE IS THE ONLY SUPPLIER AND AUTHORISED APPLICATION INSTALLER OF HYDRO G9+.



CARE INSTRUCTIONS

INTERIOR SURFACE COATINGS

LEATHER COATING

- Clean the leather surfaces of your vehicle regularly (e.g. fortnightly) using a clean damp cloth to maintain the protected surfaces.
- If a spill occurs on the treated leather surface, immediately absorb the spill with a clean non-coloured cloth. If the stain has been allowed to dry, use a non-coloured cloth dampened with mix of warm water and a pH neutral shampoo and gently rub the stained area until clean.
- If the leather surface is repaired or replaced, HYDRO G9+ Leather Coating must be re-applied to those areas. Please call 1300 801 917 to discuss any reapplication queries or to arrange reapplication.

FABRIC & CARPET COATING

- Clean/vacuum the fabric/carpet of your vehicle regularly (e.g. fortnightly) to maintain the protected surfaces.
- If a spill occurs on the treated fabric/carpet surface, immediately absorb the spill with a clean non-coloured cloth. If a stain persists or has been allowed to dry, use a non-coloured cloth dampened with mix of warm water and a pH neutral shampoo and gently rub the stained area until clean.
- If the fabric/carpet surface is repaired or replaced, HYDRO G9+ Fabric & Carpet Coating must be reapplied to those areas. Please call 1300 801 917 to discuss any reapplication queries or to arrange reapplication.

VINYL COATING

- Clean the vinyl surfaces of your vehicle regularly (e.g. fortnightly) using a clean damp cloth to maintain the protected surfaces.
- If a spill occurs on the treated vinyl surface, immediately absorb the spill with a clean non-coloured cloth. If the stain has been allowed to dry, use a non-coloured cloth dampened with mix of warm water and a pH neutral shampoo and gently rub the stained area until clean.
- If the vinyl surface is repaired or replaced, HYDRO G9+ Vinyl Coating must be re-applied to those areas. Please call 1300 801 917 to discuss any reapplication queries or to arrange reapplication.

MOTORONE IS THE ONLY SUPPLIER AND AUTHORISED APPLICATION INSTALLER OF HYDRO G9+.

